

PIONEER INDUSTRIAL RAILWAY CO.

FREIGHT TARIFF PRY - 9050

NAMING

RULES AND CHARGES

FOR

INSPECTIONS

APPLYING AT

STATIONS ON THE

PIONEER INDUSTRIAL RAILWAY CO.

INSPECTION TARIFF

ISSUED: February 28, 2018

EFFECTIVE: March 01, 2018

Issued By:

Dale Montgomery
VP of Marketing & Business
Development
Pioneer Industrial Railway
1318 So. Johanson Rd., Peoria, IL 61607

FREIGHT TARIFF PRY-9050
(CONTINUED)

INSPECTION RULES AND CHARGES

THE FOLLOWING RULES AND CHARGES ARE APPLICABLE TO INSPECTIONS ON THE PIONEER INDUSTRIAL RAILWAY CO. (PRY)

Any time any locomotive, track, bridge, culvert, signal, crossing protection device, or other railroad facility or fixture may have suffered damage due to the actions of a third party, PRY shall, as soon as is practical, perform a safety inspection of such property.

Rates for such inspections are as follows:

Locomotive inspection	\$ 750.00
Track Inspection	750.00
Signal / Crossing Protection Device	750.00
Bridge / Culvert / Trestle	1,500.00
Bridge requiring special equipment/personnel, etc.	5,000.00
Railcar	250.00
Miscellaneous facility / fixture	250.00

The above charges are to assess the extent of damage and need for repair/replacement of the track/facility/fixture. These charges do not cover the cost of such repair or replacement.

This Tariff issued under the authority of the Interstate Commerce Act, 49 U.S.C. Section 10702.

-END-
